

Product Safety Recall

**Thule Sleek Stroller
(Model numbers 11000001-11000019)**



**Sold by Go Active Outdoors and Thule Australia
between January 2019 and August 2020**

Defect Two screws that secure the handlebar to the frame may be missing. The handlebar may detach from the frame

Hazard If the handlebar detaches from the frame, there is a risk of injury to the child.

What to do Consumers should stop using the stroller. To identify whether their stroller is affected by the recall, consumers should check the model number printed on a sticker on the lower part of the stroller's frame. Consumers should also check for the presence of a QC2020 sticker, which indicates that the product has been checked and is not affected by the recall.

If affected, consumers should register their details at <https://www.thule.com/en-au/product-recall/recallthulesleek> to receive a replacement stroller frame.

Contact details Consumers can contact thulesleek19@thule.com, or visit <https://www.thule.com/en-au/product-recall/recallthulesleek>

**See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information**